



Customer Name: U.S. Micro Solutions, Inc. **Sample Date:** May 27, 2017
Customer Address: 302 Unity Plaza **Date Received:** May 28, 2017
Latrobe, PA 15650 **Date of Report:** May 29, 2017

Customer Phone: (724) 853-4047 **Fax:** (724) 853-4049
PO Number: **Attention:**
Project Name/Number:

Customer sample numbers below are uniquely identified by prefixing Laboratory # 12345-17

Direct Microscopic Examination - Tape Lift
Analytical Method: USMS-T049

Customer Sample Number	1														
Sample Description/ Location	Attic Decking														
Particle ID	Rare Amt	Few	Mod	Many	Num	Rare Amt	Few	Mod	Many	Num	Rare Amt	Few	Mod	Many	Num
Alternaria conidia															
Ascospores															
Aspergillus fruiting structures															
Aspergillus/Penicillium-like conidia		X													
Basidiospores															
Bipolaris/Drechslera conidia															
Chaetomium ascospores															
Cladosporium conidia															
Curvularia conidia															
Epicoccum conidia															
Hyphal Fragments		X													
Insect fragments															
Penicillium fruiting structures		X													
Pithomyces/Ulocladium conidia															
Plant fragments															
Pollen (unidentified)															
Rusts															
Smuts/ Myxomycetes															
Stachybotrys conidia															
Stachybotrys fruiting structures															
Torula conidia															
Unidentified dematiaceous conidia															
Unidentified hyaline conidia															
Skin Cell Fragments					1										
Debris					3***										
No fungal conidia/hyphal fragments noted															
Analyst Initials					BM										
Date Analyzed					5/28/17										

Sample Report

Results relate only to the samples tested. The *Aspergillus/Penicillium*-like category cannot be differentiated by non-viable sampling methods.
Mod = Moderate; Num = Numerous

*** A debris rating of 3 or greater indicates that the accuracy of the analysis is likely affected.

When providing duplicates of this report, the document should be provided in total and not in section in accordance with AIHA-LAP, LLC. Any unauthorized or improper disclosure, copying, distribution, use, or falsification of these results is prohibited. USMS shall have no liability to the Customer or the Customer's customer for opinions stated, recommendations made, actions taken, or conduct implemented based on the test results reported.

Technical Manager: Herbert Layman
Herbert Layman, BS, SM, CIEC

End of Report