



U.S. Micro-Solutions, Inc. \* 302 Unity Plaza \* Latrobe, PA 15650  
 Phone: (724) 853-4047 Fax: (724) 853-4049 AIHA-LAP, LLC EMLAP #103009  
[www.usmslab.com](http://www.usmslab.com)



Customer Name: U.S. Micro Solutions, Inc. Sample Date: December 18, 2017  
 Customer Address: 302 Unity Plaza Date Received: December 19, 2017  
 Latrobe, PA 15650 Date of Report: December 26, 2017  
 Customer Phone: 724-853-4047 Fax: (724) 853-4049  
 PO Number: Attention:  
 Project Name/Number: Sample Report

Customer sample numbers below are uniquely identified by prefixing Laboratory # 12345-17

Liquid Sample(s) for Heater Cooler Unit Water Culture - Analytical Method USMS-B028

Sample Number	Analysis	Sample Description	Results of Microbial Analysis
1	HPC-R2A	Operating Room A	2 CFU/mL
			Raw Count: 2
AS = 1 CFU/mL (Volume examined: 2.2 mL) Analysis Time: 8 Hrs			
1	<i>P.aeruginosa</i> - cetrimide	Operating Room A	
			10 CFU/100mL - <i>P. aeruginosa</i>
1	Coliforms- mFC	Operating Room A	
			No coliforms isolated
AS = 1 CFU/100mL			
1	Mycobacteria- 7H11	Operating Room A	
			No <i>Mycobacterium</i> spp. isolated
AS = 1 CFU/100mL			

# Sample Report

Notes:

Results relate only to the samples tested. Results are reported as calculated. For biological data, the first and/or second digit should be considered significant.

When providing duplicates of this report, the document should be provided in total and not in section in accordance with AIHA-LAP, LLC. Any unauthorized or improper disclosure, copying, distribution, use, or falsification of these results is prohibited. USMS shall have no liability to the Customer or the Customer's customer for opinions stated, recommendations made, actions taken, or conduct implemented based on the test results reported.

Technical Manager: Herbert Layman, BS, SM, CIEC

\*End of Report\*